



Doc No: **TIBFM 03-07**  
Date Issued: Dec. 05, 2018  
Date Revised: N/C

**TECHNICAL INFORMATION**  
**BULLETIN**

**Notice of Discontinued Product Support**

**Model(s) Affected:** All TDFM-136  
981087-1, 987087-2

**Effective Date:** December 5, 2018

**Reason:** Due to the age of this product, and increasingly limited part availability, Technisonic Industries Ltd. can no longer offer factory repair service for TDFM-136 Transceivers.

At the time of release of this notice, the TDFM-136B Part Number 081252-X-XX is offered as a direct, pin-compatible replacement.