



TECHNICAL INFORMATION
BULLETIN

Notice of Discontinued Product Support

Model(s) Affected: All TDFM-6000 containing Type I RF Modules
011210-1-6xxx All Projects

Effective Date: December 5, 2018

Reason: Due to discontinued support from Motorola, Technisonic Industries Ltd. can no longer offer factory repair service for TDFM-6000 Transceivers containing Type I RF Modules.

This includes "hybrid" radio projects and any radio programmed using Astro Saber CPS and the Motorola RIB Programming interface (or equivalent).

NOTE: Please contact your Technisonic Distributor for information regarding replacement options for this product.